Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,



CLEARING OVER BURDAN EARTH

photo
R. Nawkarg 24/05/19

JUSTIUS CONSULTANTS

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

Clearing Over Burden Earth & Road Formation

PLUS CONSULTANTS

Photos
K. Nanjunda 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,





LOWERRING AND LEVELLING THE GROUND

photos
K. Nantunga 20/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

REMOVAL OF OVERBURDEN EARTH

JENUS CONSULTANTS

photos
K. Nandeesha 22/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,



Clearing Over Burden Earth & Road Formation

photos
V.C. Nawalwa 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,



Clearing Over Burden Earth & Road Formation

TEJUS CONSULTANTS

photos
R. Nandini 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

WATER BOUND MECADAM

TEJUS CONSULTANTS

photos
K. Nanjunda 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

WATER BOUND MECADAM WITH CRUSHED STONE AGGREGATES

TEJUS CONSULTANTS

photos
R. Nanda 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

M.S Rectangular Pole Fixing

photos
K. Nawaz 24/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,



SITE INPECTIONS BY ENGINEERS

photos
R. Nagaraja 20/05/19

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,

NEXUS CONSULTANTS

CHAIN LINK FENCING

Photos
K. Nandan 24/05/18

Providing and fixing Chain link Fencing to abandoned Kogilu Quarry in ward no. 05,



CHAIN LINK FENCING

photos
R. Nanjunda 24/05/19

Providing and fixing Chain Link Fencing to abandoned Kogilu Quarry in ward no. 05,



TEJUS CONSULTANTS

PAINTING WORKS

photos
R. Nandan 22/05/19